STATE OF FLORIDA DEPARTMENT OF STATE

FLORIDA MASTER SITE FILE

802 = = Division of Archives, History Site Inventory Form **FDAHRM** and Records Management 1009 = =Rev. 3-79 DS-HSP-3AAA Site No. Site Name Lucien Renuart Residence 820 = = 830 = = Survey Date 8504Address of Site: 501 NE 94 Street, Miami Shores, FL 905 = =Instruction for locating on NE corner of NE 94th Street and NE 5th Avenue 813 = =868 = =13,14,15 Location: Miami Shores Sec. lot no. subdivision name = = 808Dade County: Koppen, Robert Owner of Site: Name: ___ 501 NE 94th Street Address: 902 = =Miami Shores, FL 832 = = Type of Ownership <u>private</u> 848 = Recording Date _ Recorder: Name & Title: Stofik, Marty Address: MSHPB 818 = =Original Useprivate residence 838 = = Integrity of Site: Condition of Site: Present Useprivate residence 850 = = Check One or More Check One Dates: Beginning +1935 858 = = 844 = =Altered Excellent 863 = = 840 = = Culture/Phase American X Unaltered 858 = = 863 = = Good 845 = =Period 20th Century Original Site 858 = = Fair 863 = = Restored () (Date:)() 858 = = 863 = = Deteriorated ☐ Moved () (Date:)()858 = = 916 = =NR Classification Category: Building Threats to Site: None Check One or More Transportation()()()878 = =)()878 = = Zoning ()()()878 = = ☐ Fill()()()878 = = Development ()(

)()878 = =

)()878 = =

Significance:

Deterioration ()(

Other (See Remarks Below):

Areas of Significance: Architecture

☐ Borrowing ()(

The home was built for Lucien Renuart, a member of a prominent Dade Co. business family which owned the first industry in Miami Shores, Renuart Lumber Company. The firm was established in Canada in 1923 and operated i in Miami Shores from 1925-1965. Renuart was active in civic affairs, serving as a founding member of the Board of Brockway Memorial Library. The architect, Henry VanDerLyn, served 6 years on the Miami Shores Planning and Zoning Board. The home is one of several English style homes built during the 1930s in Miami Shores. Noteworthy details include half-timber detailing on the front mass, a stained glass window above the entry door and a copper hood over the entrance.


☐ Dredge ()(

878 = =

)()878 = =

910 = =

ARCHITECT VanDerLyn, Henry	070			
	872 = =			
BUILDERThomas, Henry	874 = =			
STYLE AND/OR PERIODEnglish Cottage	964 = =			
PLAN TYPEirregular	966 = =			
EXTERIOR FABRIC(S) textured stucco	854 = =			
STRUCTURAL SYSTEM(S)concrete block	856 = =			
PORCHES none				
	942 = =			
FOUNDATION: concrete block	942 = =			
ROOF TYPE: multiple gable and hip				
SECONDARY ROOF STRUCTURE(S): (see continuation sheet)				
CHIMNEY LOCATION: C: interior, Wslope				
WINDOW TYPE: steel casement, DHS and gothic arch fixed panes				
CHIMNEY: CBS	882 = =			
ROOF SURFACING: asphalt shingles	882 = =			
ORNAMENT EXTERIOR: cast masonry, wood	882 = =			
NO. OF CHIMNEYS one 952 = NO. OF STORIES two	950 = =			
NO. OF DORMERS none	954 = =			
Map Reference (incl. scale & date) Miami Shores Village Plat 1980				
	809 = =			
Latitude and Longitude:				
· ' "	800 = =			
Site Size (Approx. Acreage of Property): LT1	833 = =			



Township	Range	Section	
53S	42E	6	812 = =


UTM Coordinates:

Zone Easting Northing

Photographic Records Numbers 85N115MS04A/85N115MS05A

860 = =

Contact Print



STATE OF FLORIDA
DEPARTMENT OF STATE
Division of Archives, History
and Records Management
DS-HSP-3E
9-74

Site No.					
	Lucien		Renuart		Residence
	501				
	Miar	ni S	Shor	res.	FL

CONTINUATION SHEET

Secondary roof (cont)

Two rear masses: gable and hip roofs; porte cochere, gable; front (S) massing has hip roof

942=

Physical Description

Structure is English Cottage style with irregular massing and multiple roof shapes. Front (S) massing has cantilevered second-story with hip roof, exposed wood joists and half-timber detailing. 1st floor has large 4-pane stained glass window. Decorative buttresses extend from E front. Central mass has gable roof, two rear masses have gable and hip roofs. Central mass entrance has copper hood above entry door and masonry coat of arms above hood. 2nd floor has gothic arch stained glass window. Stucco has "exposed brick" patches. Some portions of 2nd story are faced with horizontal weatherboard siding. Porte cochere on W has gable roof, masonry supports.

