STATE OF FLORIDA DEPARTMENT OF STATE Division of Archives, History nd Records Management

## FLORIDA MASTER SITE FILE Site Inventory Form


FDAHRM 802 = =

DS-HSP-3AAA Rev. 3-79		1009 = =
	Site No.	
Site Name Musgrave/Miller Residence	830 = = Survey Date 8504	820 = =
Address of Site: 940 NE 95 St., Miami Sh	nores, FL	905 = =
Instruction for locating on S side of NE 95t	th Street between N.E. 9th Av	e.
and N.E. 10th Ave.		013 = =
Location: see cont. sheet	olock no. lot no.	868 = =
De 1	STOCK TIO,	808 = =
Owner of Site: Name: Miller, Dean		j
Address:940 NE 95 St		
Miami Shores, FI		902 = =
Type of Ownershipprivate 848 = =	Recording Date	832 = =
- Dogordor:		
Name & Title: Stofik, Marty		
Address: MSHPB		040
	<u> </u>	818 = =
Condition of Site: Integrity of Site:	Original Use private resider	1ce030 = =
Check One Check One or More	Present Use private residen	nce850 = =
☐ Excellent 863 = ☐ Altered 858 =	= Dates: Beginning +1932	844 = =
$\bigcirc$ Good 863 = $\bigcirc$ Unaltered 858 =	= Culture/Phase <u>American</u>	840 = =
	D	
Fair $863 = $ Original Site $858 =$		
Deteriorated 863 = Restored()(Date: )()858 =		
Moved ( ) (Date: )( ) 858 =		
NR Classification Category: Building		916 = =
Threats to Site: None		
Check One or More		
Zoning()( )( )878 = =	Transportation ( )(	)( )878 = =
Development()( )( )878 = =	Fill()(	)( )878 = =
Deterioration ( )( )( )( )878 = =	Dredge ( )(	)( )878 = =
Borrowing ( )( $\chi$ )878 = =		
Other (See Remarks Below):	878 = =	
Areas of Significance: Architecture		910 = =
Alcas of orginioanos.		

Significance: Structure is in an area of Miami Shores developed during the 1930s and 1940s where frame construction and Southern Colonial and classical design predominates. Home is built of native Dade County pine and frame construction cannot be duplicated under present building codes which prohibit frame construction. Residence is situated on rear of large lot surrounded by a number of large live oak trees. Noteworthy features include a two-story entry verandah with square columns and formal entry door with multiple light transom and sidelights. The home is a designated Miami Shores landmark. The present owners, Mr. and Mrs. Dean Miller, are active community leaders.

911 = =

ARCHITECT Friis, E.P. (Miami, FL)	872 = =	
BUILDER	874 = =	
STYLE AND/OR PERIOD Southern Colonial Revival	964 = =	
PLAN TYPErectangular; irregular	966 = =	
EXTERIOR FABRIC(S) wood; horizontal weatherboard	854 = =	
STRUCTURAL SYSTEM(S) wood frame	856 = =	
PORCHES N: two-story verandah, six square columns, shed roof,		
access N	942 = =	
FOUNDATION: concrete block	942 = =	
ROOF TYPE: gable	942 = =	
SECONDARY ROOF STRUCTURE(S): porch: shed, asphalt shingles CHIMNEY LOCATION: E. end, ext.		
		WINDOW TYPE: wood DHS
CHIMNEY: brick	942 = = 882 = =	
ROOF SURFACING: asphalt shingles	882 = =	
ORNAMENT EXTERIOR: wood	882 = =	
NO. OF CHIMNEYS one 952 = NO. OF STORIES two 1/3	950 = =	
NO. OF DORMERS three	954 = =	
Map Reference (incl. scale & date) Miami Shores Village Plat 1980		
	809 = =	
Latitude and Longitude:		
• , , ,	800 = =	
Site Size (Approx. Acreage of Property): +-11	833 = =	



	Township	Range	Section	
-	53S	42E	6	812 = =
	UTM Coordin	nates:		
		,		890 = =
	Zone Easting	Northing		

Photographic Records Numbers 85N101HG03A/85N101HG04A

860 = =

Contact Print



DEPARTMENT OF STATE
Division of Archives, History
and Records Management
DS-HSP-3E
9-74

Site Name Musgrave/Miller House 940 NE 95 St.

Miami Shores, FL

## CONTINUATION SHEET

Location:

P1. of Govt., 4 beg. 100' NW corner F S200' E108.5' N220'

868=

## Physical Description:

Structure is a two-story Southern Colonial Revival home located deep on a large lot surrounded by many large live oak trees. The front (N) has a two-story entry verandah fronting the entire facade. Six square wood columns support a shed roof. Windows are DHS with shutters. There are three dormer windows on the N slope. The entry door has divided light rectangular transom and sidelights. 2nd story over entry has full-length door with balcony. Garage is to the SW of main house; double arched wood bay doors. A cross-beam fence fronts entire property.