GE Modular Space Virginia Key Beach Trust Date Reviewed: 03/23/06

Items needing Attention:

Room	Item	Who	Result
	Exterior lights - 4 floods need to be changed	_	New floods installed one
Exterior	out as per orginial request	DSI	requires a bulb element
	Exterior lights - porch lights installed crooked		_
Exterior	and loose	DSI	ok
			Work still required -
			additional settling crack
Exterior	Crack in hardi at back door	DSI	requires calking
Exterior	Missing screen in office 8	DSI	Still required
			Screws installed - screw
	Both front and back doors missing screws		heads require touch up
Exterior - Doors	around trim	DSI	paint
			Still required - Rubber
_		_	boots are needed for
Exterior - Roof	Missing roof vents	DSI	roof vents
	Electrical - please test outlets and lights -		
General	some not working	DSI	ok
	Cut moldings running behind base and	_	
Interior - Back Hall	reattach base	DSI	ok
	Went overboard on nailing of corner molding -		
	need to replace - can we look at using a wider		
	molding? That area will get considerable		
Interior - Back Hall	traffic	DSI	ok
	Cut trim board (to remove from behind base)		
Interior - Between office 7&8	and reattach base so it's flat	DSI	ok
Interior - Between office 8&9	Attach molding at base	DSI	ok
Interior - Conference Room	Re-attach trim at window	DSI	ok
Interior - Conference Room	Caulk at mateline trim	DSI	ok
	Missing ceiling trim at mateline - just inside		
Interior - Conference Room	window	DSI	ok
	Check all door casings - many of the miters		
Interior - General	pulled apart	DSI	ok
	MANY areas have popcorn overspray and		
	several - bad clean up job - smeared. It's on		
Interior - General	windows, doors, light fixtures, walls,etc	DSI	ok
	Mateline ceiling trim board outside door -		
Interior - Kitchen	caulk or re-cut a new piece that fits better	DSI	ok
Interior - Kitchen	Cleaning of popcorn done badly	DSI	ok
	Outside conference room - Mateline - cut		
	corner bead so it doesn't fall behind base and		
Interior - Main Area	re-attach base	DSI	ok
			Calking in place, some
			discoloration -
	Crack in ceiling at light fixture - near reception		additional settleing
Interior - Main Area	wall	DSI	crack has formed.
	Some boards caulked - need to do the		ok - many corner
Interior - Matelines	balance - many have gaps	DSI	moldings need finishing
			ok - many corner
Interior - Molding	Finish molding at matelines	DSI	moldings need finishing

GE Modular Space Virginia Key Beach Trust Date Reviewed: 03/23/06

Items needing Attention:

Items needing Attention: Room	Item	Who	Result
Room	item	wno	Result
	Molding does not run completely to ceiling or		ok - many corner
Interior - Molding	floor - left side of reception area	DSI	moldings need finishing
Interior - Office #1	Moling cut short at ceiling	DSI	ok
Interior - Office #1	A/C return - falling down - needs screws	DSI	ok
Interior - Office #1	Bank of lights not working	DSI	ok
interior - Office #1	Reattach (exterior wall side) wall board and	D01	OK .
Interior - Office #2	trim - whole board coming off	DSI	ok
Interior - Office #4	Needs an a/c supply	DSI	Still required
Interior - Office #4	Re-attach return - screws missing	DSI	ok
Interior - Office #4	Popcorn on light fixture	DSI	Still required
Interior - Office #5	Popcorn overspray cleaned badly	DSI	ok
Interior - Office #5	Snag in carpet	DSI	ok
Interior - Office 4	Batt molding coming off - reattach	DSI	ok
Interior - Office 7	Ceiling - hole - need repair and popcorn	DSI	ok
interior - Office 1	eciling Tible Tieed repair and popeoin	D01	Still required - spring
			loaded closers are
Interior - Restrooms	both closers are missing	DSI	needed
Interior - Restrooms	both closers are missing	וטטו	needed
	Can we change the swing of the doors to		
	swing into the main area? Do we have ADA		Code will not allow
Intoviou Doctucono		DCI	
Interior - Restrooms	or egress issues if we do? What will it cost?	DSI	change
Interior - Restrooms	Missing light cover - mens room	DSI	ok
Interior Office 8	Batt molding coming off - reattach	DSI	ok Need 3 ft base cover; 1
			-
			pc hardi panel stucco;
56 1 1111 1			kitchen window water
DSI additional notes		DSI	leak repair is required;
Exterior	Pressure Wash	GE	
Exterior	General site clean up - trash, etc	GE	
	Run lines from A/C condensation drains from		
Exterior	the units to the ground (off the slab)	GE	
Interior - General	General clean	GE	
Interior - Restrooms	Need Men/Women	GE	
Exterior	Give requirement for handicap space	GE - Kristine	
	Around plumbing clean out at the back of the		
Exterior	building - fill dirt in around	Losa	
	Dispose of/remove concrete over spill, broken		
	blocks, conduit left behind, saw horses, etc		
Exterior	from the site	Losa	
	Why can't the panels be locked in the "on"		
	position? Looks like the lock plates where		
	installed upside down? Or is it a safety issue		
Exterior - Electrical Deck	to not lock them in the "on" position?	Losa	
	Fix concrete pad below boxes and remove the		
	form boards - concrete not finished and left to		
Exterior - Electrical Deck	dry uneven.	Losa	
	The left side ground is about a foot away from		
Exterior - Electrical Deck	the slab - move closer	Losa	
Exterior - Parking	Parking stops not anchored	Losa	
			ì

GE Modular Space Virginia Key Beach Trust Date Reviewed: 03/23/06

Items needing Attention:

Room	Item	Who	Result
	Handicap symbol stenciled on the parking		
Exterior - Parking	spot very sloppy - please point up	Losa	
Exterior - Parking	Unused conduit left open - fill and finish	Losa	
	Customer has concern that holes left open int		
	the bottom of the newell posts with be a home		
Exterior - Decks	for wasps - anything that can be done?	T&S	
Exterior - Decks	Rust and Touch up needed throughout	T&S	
	Many screws in the decking rusting - did the		
Exterior - Decks	wrong ones get used?	T&S	
Exterior - Decks	Loose planks various places	T&S	
Exterior - Decks	Steps - Slick when wet	T&S	
	Can yellow and black warning tape be		
Exterior - Decks	adhered to the edge?	T&S	
	Handrail on h/c ramp - doesn't wrap and		
	protrudes into the walkway, needs to be cut		
Exterior - Decks	and welded to wrap.	T&S	
	Gap and lip at decking near front door (where		
Exterior - Decks	2 sections meet)	T&S	
	Re-attach the skirting on the left side of the		
Exterior	building	V&J	
	Fix the hole in the hardi - left side, front corner		
Exterior	of building	V&J	
	Humps in roof - as previously requested for		
Exterior - Roof	repair	V&J	
Interior - main Area	Base between office 4 and 5 missing	V&J	
Interior - Main Area	Base between office 5 and 6 missing	V&J	