Room	Item	Who	Result
	Exterior lights - 4 floods need to be changed		
Exterior	out as per orginial request	DSI	ok 4/12/06
	Exterior lights - porch lights installed crooked		
Exterior	and loose	DSI	ok
Exterior	Crack in hardi at back door	DSI	ok 4/12/06
Exterior	Missing screen in office 8	DSI	ok 5/4/06
	Both front and back doors missing screws		
Exterior - Doors	around trim	DSI	ok 5/4/06
Exterior - Roof	Missing roof vents	DSI	ok 5/4/06
	Electrical - please test outlets and lights -		
General	some not working	DSI	ok
	Cut moldings running behind base and		
nterior - Back Hall	reattach base	DSI	ok
	Went overboard on nailing of corner molding -		
	need to replace - can we look at using a wider		
	molding? That area will get considerable		
Interior - Back Hall	traffic	DSI	ok
	Cut trim board (to remove from behind base)		
Interior - Between office 7&8	and reattach base so it's flat	DSI	ok
nterior - Between office 8&9	Attach molding at base	DSI	ok
nterior - Conference Room	Re-attach trim at window	DSI	ok
nterior - Conference Room	Caulk at mateline trim	DSI	ok
	Missing ceiling trim at mateline - just inside		
nterior - Conference Room	window	DSI	ok
	Check all door casings - many of the miters		
Interior - General	pulled apart	DSI	ok
	MANY areas have popcorn overspray and		
	several - bad clean up job - smeared. It's on		
Interior - General	windows, doors, light fixtures, walls,etc	DSI	ok

Room	Item	Who	Result
	Mateline ceiling trim board outside door -		
Interior - Kitchen	caulk or re-cut a new piece that fits better	DSI	ok
Interior - Kitchen	Cleaning of popcorn done badly	DSI	ok
	Outside conference room - Mateline - cut		
	corner bead so it doesn't fall behind base and		
Interior - Main Area	re-attach base	DSI	ok
	Crack in ceiling at light fixture - near reception		
Interior - Main Area	wall	DSI	ok 5/4/06
	Some boards caulked - need to do the		
Interior - Matelines	balance - many have gaps	DSI	ok 4/12/06
Interior - Molding	Finish molding at matelines	DSI	ok 4/12/06
	Molding does not run completely to ceiling or		
Interior - Molding	floor - left side of reception area	DSI	ok 4/12/06
Interior - Office #1	Moling cut short at ceiling	DSI	ok
Interior - Office #1	A/C return - falling down - needs screws	DSI	ok
Interior - Office #1	Bank of lights not working	DSI	ok
	Reattach (exterior wall side) wall board and		
Interior - Office #2	trim - whole board coming off	DSI	ok
Interior - Office #4	Needs an a/c supply	DSI	ok 4/12/06
Interior - Office #4	Re-attach return - screws missing	DSI	ok
Interior - Office #4	Popcorn on light fixture	DSI	ok 4/12/06
Interior - Office #5	Popcorn overspray cleaned badly	DSI	ok
Interior - Office #5	Snag in carpet	DSI	ok
Interior - Office 4	Batt molding coming off - reattach	DSI	ok
Interior - Office 7	Ceiling - hole - need repair and popcorn	DSI	ok
			Spring closers not
			recommended with this
Interior - Restrooms	both closers are missing	DSI	type of door - ok

Room	Item	Who	Result
Interior - Restrooms	Can we change the swing of the doors to swing into the main area? Do we have ADA or egress issues if we do? What will it cost?	DSI	ok 4/12/06 - Code will not allow change
Interior - Restrooms	Missing light cover - mens room	DSI	ok
Interior Office 8	Batt molding coming off - reattach	DSI	ok
DSI additional notes		DSI	Need 3 ft base cover; 1 pc hardi panel stucco; window ok 4/12/06

GE Modular Space Virginia Key Beach Trust

Date Reviewed: 05/4/06

Room	Item	Who	Result
Exterior	Pressure Wash	GE	ok 4/24
Exterior	General site clean up - trash, etc	GE	ok 4/24
	Run lines from A/C condensation drains from		
Exterior	the units to the ground (off the slab)	GE	ok 4/26
Interior - General	General clean	GE	ok
Interior - Restrooms	Need Men/Women	GE	ok 4/26
Exterior	Give requirement for handicap space	GE - Kristine	ok

Room	Item	Who	Result
	Around plumbing clean out at the back of the		
Exterior	building - fill dirt in around	Losa	Still required
	Dispose of/remove concrete over spill, broken		
	blocks, conduit left behind, saw horses, etc		
Exterior	from the site	Losa	ok 4/24
	Why can't the panels be locked in the "on"		
	position? Looks like the lock plates where		
	installed upside down? Or is it a safety issue		
Exterior - Electrical Deck	to not lock them in the "on" position?	Losa	Still required
	Fix concrete pad below boxes and remove the		
	form boards - concrete not finished and left to		Still required - wood
Exterior - Electrical Deck	dry uneven.	Losa	framing was removed
	The left side ground is about a foot away from		
Exterior - Electrical Deck	the slab - move closer	Losa	ok
Exterior - Parking	Parking stops not anchored	Losa	ok - messy epoxy runoff
	Handicap symbol stenciled on the parking		
Exterior - Parking	spot very sloppy - please point up	Losa	Still required
Exterior - Parking	Unused conduit left open - fill and finish	Losa	ok -messy

Room	Item	Who	Result
	Customer has concern that holes left open int		
	the bottom of the newell posts with be a home		
Exterior - Decks	for wasps - anything that can be done?	T&S	ok 4/23
Exterior - Decks	Rust and Touch up needed throughout	T&S	ok
	Many screws in the decking rusting - did the		
Exterior - Decks	wrong ones get used?	T&S	ok
Exterior - Decks	Loose planks various places	T&S	ok
Exterior - Decks	Steps - Slick when wet	T&S	ok 4/23
	Can yellow and black warning tape be		
Exterior - Decks	adhered to the edge?	T&S	ok 4/23
	Handrail on h/c ramp - doesn't wrap and		
	protrudes into the walkway, needs to be cut		
Exterior - Decks	and welded to wrap.	T&S	ok
	Gap and lip at decking near front door (where		
Exterior - Decks	2 sections meet)	T&S	ok

Room	Item	Who	Result
	Re-attach the skirting on the left side of the		
Exterior	building	V&J	ok
	Fix the hole in the hardi - left side, front corner		
Exterior	of building	V&J	ok 4/26
	Humps in roof - as previously requested for		
Exterior - Roof	repair	V&J	ok 5/4/06
Interior - main Area	Base between office 4 and 5 missing	V&J	ok
Interior - Main Area	Base between office 5 and 6 missing	V&J	ok