

**Renovations & Repairs Project  
Repair Report: 1/26/06**




Baseboard water damage in concession stand building at Virginia Key Beach Park



Baseboard water damage in concession stand building at Virginia Key Beach Park



Baseboard water damage in concession stand building at Virginia Key Beach Park



Window sill water damage in concession stand building at Virginia Key Beach Park



Exterior cracks surrounding the restroom window of the concession stand building



Close up of exterior cracks surrounding the restroom window of the concession stand building



Wall on Northern end of the carousel building cracking



Exterior cracks surrounding the office window area at concession stand building at Virginia Key Beach Park



Light switch installed behind the door of men's handicapped restroom in bathhouse at Virginia Key Beach Park



Wall on Northern end of the carousel building cracking



Water damage near ceiling of women's restroom in bathhouse at Virginia Key Beach Park



Water damage near ceiling of women's restroom in bathhouse at Virginia Key Beach Park




Exterior lighting does not meet codes for protected sea turtle nesting on bathhouse at Virginia Key Beach Park



Water damage near ceiling of men's restroom in bathhouse at Virginia Key Beach Park



Baseboard water damage in janitor closet in concession stand building at Virginia Key Beach Park



Exterior paint peeling on concession stand building at Virginia Key Beach Park



Baseboard water damage in janitor closet in concession stand building at Virginia Key Beach Park