

CIP/VKBPT Meetings – August 24, 2005

Concession Stand Building

There are water damage leaks in both restrooms in the concession stand building Room #104 & #105.

The door lock doesn't operate on the storage door Room #112

The electrical outlet for the Fryer machine in the concession stand building does not fit the appliance – must be changed.

Roll up door repair is needed – poor installation

Bath House Building

There are water damage leaks in both the male and female restrooms in the bath house – possibly from the sky lights.

The motion detector light must be installed in the handicapped restrooms in the bath house building.

Carousel Building

Serious cracking on the carousel building structure – photo was e-mailed.

Roll up door repair is needed – may only need lubrication.

Sanitary Sewer – Lift Station

Energizing the lift station

Tests

Timeframe

Parking Lot Improvements & Circulation Road

Storm water drainage design

Parking lot lighting design – review is needed

Timeframe

September Meeting:

Regosa renovation and repairs project improvements.

Concession Stand Building

There are water damage leaks in both restrooms in the concession stand building Room #104 & #105.

The door lock doesn't operate on the storage door Room #112

The electrical outlet for the Fryer machine in the concession stand building does not fit the appliance – must be changed.

Roll up door repair is needed – poor installation

Bath House Building

There are water damage leaks in both the male and female restrooms in the bath house – possibly from the sky lights. Evidence of water damage in the roof/ceiling areas.

The motion detector light must be installed in the handicapped restrooms in the bath house building.

Carousel Building

Serious cracking on the carousel building structure – photo was e-mailed.

Roll up door repair is needed – may only need lubrication.

Sanitary Sewer – Lift Station

Energizing the lift station

Tests

Timeframe

Parking Lot Improvements & Circulation Road

Storm water drainage design

Palm tree planting in the bus passenger drop off section

Parking lot lighting design – review and approval is needed from Florida DEP

Timeframe – punch list review