VILLAGE OF MIAMI SHORES

LANDMARK FACT SHEET

WORK SHEET

NAME	Lucien Renuart Residence	DATE 11/21/83
LOCATION	501 N.E. 94th Street, Miami Shores	
CLASSIFICA	ATION structure CATEGORY	residential
PERMIT NO.	DATE CONSTRUCTED 1935	CONDITION good
ARCHITECT	Henry O. VanDerLyn BUILDER H	lenry M. Thomas
ORIG. OWNE	R Lucien Renuart PRE	SENT OWNER & ADDRESS
	Robert Koppen	
	501 N.E. 94th Street, Miami Shores	
CURRENT ZO	DNING R-17.5 - residential	

SIGNIFICANCE: A - A physical (architectural or archeological) description of the site. Photograph should accompany this description.

Two-story English cottage-style structure; masonry/stucco construction. Plan is irregular. East section has cantilevered second-story with hip roof, exposed wood joists and half-timber detailing on second story. Large four-pane stained glass window centers first story. Decorative buttress extends from east front. Central mass has gable roof, interior chimney. Modern wood entry door; brass hood above door; masonry coat of arms above hood. Second story has stained glass gothic arch window. Windows have brick sills. One bay carport on west side has gable roof, elliptical arch opening. Asbestos shingle roof, repaired with fiberglass shingles. Stucco has exposed brick patches.

SIGNIFICANCE: B - A brief description of the site's relationship to the history, development, architecture, archeology and/or culture of Miami Shores, Dade County, the State of Florida or the nation.
The original owner of the house, Lucien Renuart, was a member of a prominent
Dade County business family which owned Renuart Lumber, one of the few early
industries in Miami Shores. The firm was established in Canada in 1923 and
operated in Miami Shores from 1925-1965. Mr. Renuart was active in civic
affairs, served as a member of the founding board of Brockway Memorial
Library, and served as President of Optimist International. The architect,
Mr. VanDerLyn, served for six years on the Miami Shores Planning and Zoning

j.

,

		P.	AGE 2 -	LANDMARK S	UMMARY SH	EET	
	HISTORICAL SU	JMMARY (con	tinued)	2 2 			
	Board. This	s house is	an unusual	style in	Miami Sho	res and	is signifi
	for its deta	ailing and	size.				5
			er.				
					 		
	ана 1 1 - С. 		**************************************				

	HISTORIC DIST INDIVIDUAL SI	TRICT REPOR	TS WILL CO HE ADDITIO	NTAIN THE N OF THE F	SAME INFO OLLOWING:	RMATION	AS THOSE F
	1) DATA:	A man and the		dam of the			
	Α.	A map with buildings,	streets a	nd major t	opographi	, proper cal feat	tures.
	12 ¥ 0 ¥						
		ан ^а д. 1995.					.
	Ъ ⁴	Σ.			е Э		
	f to e	1 N I		*			
	1						
				a.			
	• * *	2 6 7 2					
	de la constante de la constante La constante de la constante de						5
	5 X	9 •					
	2 5						
	2) STONTETCA	NCF			· .		
		ANCE: A brief de within the relationsh as a whole	district ip to the	to each ot	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
·	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and t	he dist	ric-'s
	Α.	A brief de within the relationship	district ip to the	to each ot surroundir	her and the area a	he dist	ric-'s
a a a a a a a a a a a a a a a a a a a	A.	A brief de within the relationship	district ip to the	to each ot surroundir	her and the area a	he dist	ric-'s
	A.	A brief de within the relationsh as a whole	district ip to the	to each ot surroundir	her and the area a	he dist	ric-'s

2/79	DADE COUNTY H	ISTORIC SURVEY	FDAHRM	802=
,	SITE INVE	NTORY FORM	Site No.	1009=
Site Name (Addre	ss)501 N.E. 94th St	reet		905=
	Site			930=
				<u>906</u> =
City & Zip Code	ite Miami Shores			813=
-	······································			01)-
subdivi				******
	1		2	868-
block no.	lot no.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,	
CountyDade	808==	Survey Date	8005	820=
	Name:			
				902=
Version and the second s	ander segner en en andere de konstant en de seine de sein			902=
Occupant, Tenant	, or Manager: Name:			90 4=
Type of Ownershi	p:		ts to Site:	
数 Private	848== Remarks	s: <u>'</u> <u>'</u>	loning ()	878
Corporate	848==		evelopment ()	878
Municipal	848==		eterioration ()	878
	848==		ransportation () Other (See Remarks):	878 878
Condition of Sit	e:.	• -		
Excellent	863==		rity of Site: Altered	858
XXGood	863==		Inaltered	858
$\Box \frac{\text{Fair}}{\text{Deteriorated}}$	863==		Driginal Site	858
	003==		Restored () Date:	
Remarks:			loved () Date:	
••••••••••••••••••••••••••••••••••••••	dan alam dan dalam dalam dan seban dan dalam dan		Destroyed () Date:	858
Reporter (or loc				
Name: Rodri	guez, Ivan A. (Dade Co	ounty Historic	Survey)	
Address: _[ade County Park and Re	ecreation Depa	rtment	
	0 S.W. 32 Road; Miami	, Florida 331	29	816
Name of Proj	ect: Dade County His	toric Survey		980
Recorder:				
Name & Title	: Monroe, Elizabet	h B. (HSS)		
Address:	FDAHRM ·			818
and and a second se	s): enter_activity/ti	tle of survey,	/name/date/repository)	
				839
UTM Coordinates	aan ah daddada da da daa ah a			
	8	1		890
Zone	Easting	Northin	Ig	
1			-	
Photographic Rec	ord Numbers 80Da03 ¹	(frames 29.	30)	860=

× . .

Address: 501 N.E. 94th Street

Significance:

The residence at 501 N.E. 94th Street was constructed in 1935. The original and current owner of the house is Lucien L. Renuart who was the manager of the Miami Shores branch of Renuart Lumber Yards, Inc. Several Renuart brothers lived in Miami. They were a prominent business family in Coral Gables, as well as Miami Shores. The Renuart Lumber Company was established in Winepeg, Canada in 1923. Lucien's brother, Adehemar was president of the company in Miami. The family also owned a realty company located in Coral Gables.

This masonry construction residence represents a fine example of English cottage architecture in Dade County. It is architecturally noteworthy for its half timber details and large size.

911==

Bibliography: Unpublished Source

Miami Shores, Florida. Building and Zoning Department. Building Permits, January 1925 to present.

Published Sources

Polk, R. L. R. L. Polk and Company's Miami City Directory. Jacksonville, Florida: R. L. Polk and Company.

Real Estate Data Inc., Realdex. 1980. Miami, Florida.

920==

1	
Original Use:	
E Private Residence	838==
Apartment Building	838==
D Hotel	838==
Commercial	838==
D Other:	
	838==
Present Use:	
XX Private Residence	850==
Apartment Building	850==
🗆 Hotel	850==
🖸 Commercial	850==
Cl Other:	
	£50==
Culture/Phase American	840==
Specific Dates: Beginning	1935

Areas of Significance:	
Archi tecture	910==
Commerce	910==
□ Exploration & Settlement	910==
🗆 Social/Humanitarian	910==
D Other:	
,	910==
	910==
Period:	
20th Century	845==
19th Century	845==

N.R. Classification Category: Building 916==

844==

Site No.

.

Site Name 501 N.E. 94th Street

.

STATE OF FLORIDA DEPARTMENT OF STATE Division of Archives, History and Records Management DS-HSP-3G 6-76

. .

.

.

.

ARCHITECTURAL SITE DATA SUPPLEMENT	
ARCHITECT Henry 0. Van Der Lyn	872==
BUILDER Henry M. Thomas	874==
STYLE AND/OR MODE English cottage	964==
PLAN TYPE Irregular	966==
EXTERIOR FABRIC(S)	854==
STRUCTURAL SYSTEM(S)	856==
FEATURE OF STRUCTURE (942):	
FOUNDATION:	942==
ROOF TYPE: Hip	942==
SECONDARY ROOF STRUCTURE(S):	942==
CHIMNEY LOCATION: Exterior on right side of house	942==
WINDOW TYPE: Casement #8/8, 1; wood; D.H.S. #6/6: wood; stained glass	942==
MATERIALS (882):	
CHIMNEY: Same as exterior fabric	882==
ROOF SURFACING: Asbestos shingles	882==
INTERIOR WALLS:	882==
CINAMENT INTERIOR:	882==
ORNAMENT EXTERIOR:	882==
QUANTITATIVE DATA (950-960):	
NO. OF STOREYS	950==
NO. OF CHIMNEYS	952==
OTHER (SPECIFY)	954==
	956==

ARCHITECTURAL SITE DATA SUPPLEMENT

0

•

۰ <u>۱</u>

.

MAIN ENTRANCE: Direction: south, Location: offset right, Material: wood, brack Modern wood door two brick steps up. Brass hood above door. Masonry coat of arms above all. WINDOW PLACEMENT: WINDOW PLACEMENT: WINDOW SURROUNDS AND DECORATION&rick sills. Second story cantilevered room windows have half-timber. PORCHES, VERANDAS, GALLERIES AND BALCONIES: EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side with gable roof.		
Modern wood door two brick steps up. Brass hood above door. Masonry coat of arms above all. WINDOW PLACEMENT: WINDOW SURROUNDS AND DECORATION Brick sills. Second story cantilevered room windows have half-timber. PORCHES, VERANDAS, GALLERIES AND BALCONIES: EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detail OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side		-
of arms above all. WINDOW PLACEMENT: WINDOW SURROUNDS AND DECORATION Brick sills. Second story cantilevered room windows have half-timber. PORCHES, VERANDAS, GALLERIES AND BALCONIES: EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detail OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side	E: Direction: south, Location: offset right, Material: wood,	
WINDOW SURROUNDS AND DECORATION Brick sills. Second story cantilevered room windows have half-timber. PORCHES, VERANDAS, GALLERIES AND BALCONIES: EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detail OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side	oor two brick steps up. Brass hood above door. Masonry coat	
room windows have half-timber. PORCHES, VERANDAS, GALLERIES AND BALCONIES: EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side	MENT:	
room windows have half-timber. PORCHES, VERANDAS, GALLERIES AND BALCONIES: EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side		•
PORCHES, VERANDAS, GALLERIES AND BALCONIES: EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detail OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side	UNDS AND DECORATION:Brick sills. Second story cantilever	ed
EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY): and asbestos shingle hip roof. One bay carport on right side	nave half-timber.	
EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side		
EXTERIOR ORNAMENT AND COLOR: Exposed brick patches. Battered masonry and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side	ANDAS, GALLERIES AND BALCONIES:	
and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side		
and brick chimney. Stained glass windows on first story. INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side		
INTERIOR COMMENTS: Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side	AMENIAND CULUH: Exposed brick patches. Battered masonry	
Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side		
Cantilevered mass with exposed wood joists, half timber detai OTHER (SPECIFY):and asbestos shingle hip roof. One bay carport on right side	MENITO,	
and assesses shingle mp root. The bay carpore on right side	<u>vicinits:</u>	
and assesses shingle mp root. The bay carpore on right side		
and assesses shingle mp root. The bay carpore on right side	· · · ·	
and assesses shingle mp root. The bay carpore on right side		taili
with gable roof.	Cantilevered mass with exposed wood joists, half timber de	ide
	and assestes shingle mp root. One bay carpore on right s	
DR ALTERATIONS (FREE TEXT) (857==):	and assestes shingle mp root. One bay carpore on right s	
	of.	

876== OUTBUILDINGS (FEATURES OF SITE) (876==): 876== 876== . 876== 876== •

SURROUNDINGS (CLASSIFICATION) Residential	864==
RELATIONSHIP TO SURROUNDINGS (FREE TEXT) (859==):	859== 859==
	859== 859==
·	859==

KOPPEN & WATKINS

ATTORNEYS AT LAW

SUITE 605 7900 N.E. SECOND AVENUE LITTLE RIVER, MIAMI, FLORIDA 33138 TELEPHONE (305) 754-5442

> OF COUNSEL BARBARA NORTH BURTON

ROBERT A. KOPPEN J. HERBERT WATKINS, JR. R. DANIEL KOPPEN GEORGE M. EVANS GEORGE J. LOTT ALAN S. WALTERS CURTIS J. HERBERT

November 2, 1983

Miami Shores Historic Preservation Board Mrs. Marty Stofick, Chairman 10050 N.E. 2nd Avenue Miami Shores, FL 33138

Dear Mrs. Stofick:

Thank you for your letter of October 25, 1983, relative to my home located at 501 N.E. 94 Street, Miami Shores.

I am unwilling to accept the nomination, and respectfully request that my property be deleted from the agenda for your November 21, 1983, meeting.

I trust that this written notice of my position will be sufficient, but if further action is required on my part to decline the nomination then you may either call me at my office (754-5442) or at my home (757-9566), or communicate by letter, otherwise I will conclude that no further action is required.

Very truly yours,

ROBERT A. KOPPEN

RAK/sh

KOPPEN & WATKINS

ATTORNEYS AT LAW

SUITE 605 7900 N.E. SECOND AVENUE LITTLE RIVER, MIAMI, FLORIDA 33138 TELEPHONE (305) 754-5442

March 8, 1984

ROBERT A. KOPPEN J. HERBERT WATKINS, JR. R. DANIEL KOPPEN GEORGE M. EVANS GEORGE J. LOTT ALAN S. WALTERS CURTIS J. HERBERT OF COUNSEL LEONARD DUDZIAK

-

Ms. Marty Stofik Miami Shores Village 10050 Northeast Second Avenue Miami Shores, Florida 33138

> IN RE: 501 Northeast 94th Street Miami Shores, Florida 33138

Dear Ms. Stofik:

Thank you for your kind letter of March 2, 1984.

I do respectfully decline the nomination of my house to be designated as a historical landmark of Miami Shores.

It is my understanding that without my consent, such designation will not be made. If I am in error, then I ask that you benefit me with your advice, for that I have no present plan to attend the meeting of March 19, 1984.

traly yours, Very Robert

RAK/smw

HopkinsLegal 1980 V016 pg1 Miami Sitores See # Z 10-37 4 マイ 13 IM 15 6 NE. NB 94 ST 502 1925 Map pa 40 NBOB





501 N.E. 94 SH.

STATE OF FLORIDA DEPARTMENT OF STATE Division of Archives, History and Records Management

FLORIDA MASTER SITE FILE Site Inventory Form

	rchives, History 6 Management	Site Invento	ory Form	FDAHRM	802 = =
DS-HSP-3AAA	Rev. 3-79				1009 = =
	ucien Renuart	Residence	Si	te No.	
Site Name	tax 501 NE 04	Street, Miami	630 = =	Survey Date 8	504 820 = = 905 = =
		corner of NE 9			
instruction for	locating on NE	COINCI OI NE 3		and NL JUI AV	813 = =
Location: Mia	mi Shores Sec.	2	55	13,14,15	868 = =
County: Dad	subdivision name	b	lock no.	lot no.	808 = =
Owner of Site:	Name: Kopp	en. Robert			•
Address:	501	NE 94th Street			
	Mian	i Shores, FL			902 = =
Type of Owi	nership <u>private</u>	≥ <u>848 = =</u>		Date	
Recorder:					
Name & 1	Fitle: <u>Stofik, Ma</u>	irty			
Address:	MSHPB	1.			818 = =
Condition of S	ite: Integrity	of Sito:	Original	seprivate resid	
	me. megniy	or one.	Original u	Septitate rest	
Check One		One or More	Present U	seprivate resid	dence 850 = =
X Excellent 8	B63 = = Altered	858 = =	Dates: Be	eginning +1935	844 = =
Good 8	B63 = = X Unaltered	858 = =	Culture/Pl	nase <u>America</u>	
Fair E	863 = = 🛛 Original S	ite 858 = =	Period	20th Cent	ury 845 = =
Deteriorated 8		()(Date:)()858 = =			
	Moved () (Date:)() 858 = =	-		
NR Classifica	tion Category:		-	e	916 = =
Threats to S		······································			
	Check One or More				
Zoning()()()878 = =	Transportatio	n ()()() 878 = =
	<u>()</u>				
	()(
	X				
Other (See Re			878 = =		
Areas of Sid	onificance: Archi	tecture			910 = =
a and the second s				NAME AND ADDRESS OF A DESCRIPTION OF A D	

Significance:

The home was built for Lucien Renuart, a member of a prominent Dade Co. business family which owned the first industry in Miami Shores, Renuart Lumber Company. The firm was established in Canada in 1923 and operated i in Miami Shores from 1925-1965. Renuart was active in civic affairs, serving as a founding member of the Board of Brockway Memorial Library. The architect, Henry VanDerLyn, served 6 years on the Miami Shores Planning and Zoning Board. The home is one of several English style homes built during the 1930s in Miami Shores. Noteworthy details include half-timber detailing on the front mass, a stained glass window above the entry door and a copper hood over the entrance.

911 = =

				872 = =
BUILDER Thomas, Henry	5 			874 = =
STYLE AND/OR PERIOD English_Cottage		·····		964 = =
PLAN TYPE		• • • • • • • • • • • • • • • • • • •		966 = =
EXTERIOR FABRIC(S) textured stucco			,	854 = =
				856 = =
PORCHES none	71.2			942 = =
FOUNDATION: concrete block		··· <u>···</u> ······	<u></u>	942 = =
ROOF TYPE: multiple gable and hip				942 = = 942 = =
SECONDARY ROOF STRUCTURE(S): (see conti	inuation she	et)		942 = =
CHIMNEY LOCATION: C: interior, Wslope	induction She		•	942 = =
WINDOW TYPE: steel casement, DHS and go	othic arch f	ixed pan	es	942 = =
CHIMNEY: CBS				882 = =
ROOF SURFACING: asphalt shingles				882 = =
ORNAMENT EXTERIOR: cast masonry, wood	а а			882 = =
NO. OF CHIMNEYS one 952 = =	NO. OF STOR	IES two		950 = =
NO. OF DORMERS none				954 = =
Map Reference (incl. scale & date) Miami Shores	Village Pla	at 1980		
		2. V		809 = =
Latitude and Longitude:				
0 <i>i ii</i> 0	,	" 		= = 008
Site Size (Approx. Acreage of Property): LT1				833 = =
······································			0	1
LOCATION SKETCH OR MAP N	Township	Range	Section	
	53S	42E	6	812 = =
	UTM Coordir	nates:	l	
N.E. 95 ST.	0			
1 a	Zone Easling	Northing		890 = =
4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Long Luoning			
No. I way that				
M.E. 94 ST				
WEAM 1999 705 132 75				
Ed 14/15 14/15 10/19 20/21 22 23				
10				
N.E. 93 ST.				
501 N.E. 94 ST.				
	*			
85N115MS044	VOENT 1 SMOOLA			860 = =

Photographic Records Numbers 85N115MS04A/85N115MS05A

860 = =

Contact Print

