Project	Description	Update
•	New door handles and deadbolt	Dido received DO
L o alcoma ida		Bids received, PO
Locksmith	locks for VKBPT office	must be developed
	General pest control services,	
Pest Control	spraying for facilities on VKBP	Must go out for bid
	Mini blinds installation for VKBPT	
Window Treatments	office	Near completion
	45% light transmission film for	Went out for bids;
Window Tinting	windows at VKBPT office	awaiting responses
	Shade and rain protection	Went out for bids;
Awnings	awning system for VKBPT office	awaiting responses
7.Willingo		Went out for bids;
		responses received
		project will be
	Protective sealant for concession	' <i>'</i>
Protoctive Coating	stand tile countertop	Staff
Protective Coating	Installation of three flag poles on	Jian
Flag Poles	VKBP	Must as out for hid
		Must go out for bid
Etas Alassa Massitasias	Dialing systems for fire alram in	Bids received, PO
Fire Alarm Monitoring	concession stand bldg.	must be developed
		PO developed -
	Fire extinguisher inspection -	inspections
Fire Extinguishers Inspection	Annual	scheduled
	Ext & Int. painting and touch up	
Painters	for facilities on VKBP	Must go out for bid
	Creation and installation of park	
	informational signs and banners	
Signs and Banners	for VKBP	Must go out for bid
	Exotic tree removal and land	
Tree Removal	clearing	Must go out for bid
	Hurricane readiness & cleanup	
Emergency Services	at VKBP	Must go out for bid
	General landscaping, tree	
Landscaping	trimming & gardening for VKBP	Must go out for bid
	Provide detailed ariel photos of	Must go out for blu
Manning	•	Must as sut for bid
Mapping	VKBP	Must go out for bid
	Concession stand and other	
	concessionaire operations are	
Restaurant Services	needed	Must go out for bid
	A sailboat run a-ground during	
	Hurricane Wilma is on VKBPT	
	property and requires	
Boat Removal	professional removal.	Must go out for bid